Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 9/27/2012, 9/28/2012	Man Days: 2
Inspection Unit: AMEREN ILLINOIS COMPANY - Tuscola	
Location of Audit: Tuscola	
Exit Meeting Contact: Dallas Jett	
Inspection Type: Standard Inspection - Field Audit	
Pipeline Safety Representative(s): Randall Stewart	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

Headquarters Address Information:	300 Liberty		
	Peoria, IL 61602		
	Emergency Phone#:		
	Fax#:		
Official or Mayor's Name: Ron Pate			
	Phone#: (217) 424-6518		
	Email:		
Inspection Contact(s)	Title	Phone No.	
Dallas Jett	Quality Assurance Superintendent		
John Reardon	Pressure Regulation		
Fred Halabi	Corrosion Specialist		

	CUSTOMER METER & REGULATOR	Status
Category Comment:		
PE service lines. 19 meter	ntains 22 residences between Crestview to Parkside. The mains consist of 2" welded steel installed in 19 sets were inspected on Holiday Drive from Crestview to Parkside. Not inspected were 117 and 214 Holida h staff could not gain access to the meter set due to a dog in the fenced in back yard.	
192.353(a)	Is the customer meter and regulator installed in a readily accessible location and protected from corrosion and other damage, including if installed outside a building, vehicular damage that may be anticipated?	Satisfactory
192.355(b)(1)	Is the customer regulator vent rain and insect resistant?	Satisfactory
192.355(b)(2)	Is the customer regulator vent located where gas from the vent escapes freely into the atmosphere and away from building openings?	Satisfactory

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

192.355(b)(3)	Is the vent protected from damage caused by submergence in areas of flooding?	Satisfactory
192.357(a)	Is the customer meter and regulator installed to minimize anticipated stresses upon connecting piping?	Satisfactory
192.357(d)	Is a customer regulator that might release gas vented to the outside atmosphere?	Satisfactory
192.359(a)	Is the meter operating pressure within the allowable limits of the meter case rating?	Satisfactory
192.365(a)	Is the service line valve upstream of the regulator or meter?	Satisfactory
192.365(c)	Is the service line valve located in a curb box or stand pipe that allows for ready operation?	Unsatisfactory
Issue Comment:		
leaving only the top of t detected at the regulate	oliday Drive was noted to have a buried stopcock. A brick patio had been constructed around the service line to the nut visible. Ameren exposed the service line and replaced the stopcock. While performing a follow-up insp It vent. The customer was not at the residence. The regulator will be replaced. At the close of this audit a pipe It ator is in the process of being replaced.	ection a class 3 leak was
192.727(d)	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?	Not Applicable
General Comment:		
Service had not been d	scontinued to any customer meter set inspected during this audit.	
	CATHODIC PROTECTION	Status
192.463(a)	Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?	Satisfactory
192.465(a)	Were pipe to soil readings taken?	Satisfactory
General Comment:		
The following pipe to so T-002-006-TP at the Pa Take point T-002-005-T T-002-002-TP 9 Hillcres	hland Dr South -1.156vdc hland Circle -1.167vdc	
The following pipe to so T-002-006-TP at the Pa Take point T-002-005-T T-002-002-TP 9 Hillores T-002-003-TP 404 Sou T-002-007-TP 601 Sou T-001-024-TP Proud M.	il readings were also obtained by Fred Halibi, Corrosion Specialist at the following test points: nhandle Take point Panhandle -1.81vdc / Ameren -1.67vdc P Ameren side -1.04vdc at Dr1.166vdc hland Dr South -1.156vdc hland Circle -1.167vdc	Not Applicable
The following pipe to so T-002-006-TP at the Pa Take point T-002-005-T T-002-002-TP 9 Hillores T-002-003-TP 404 Sou T-002-007-TP 601 Sou T-001-024-TP Proud M.	il readings were also obtained by Fred Halibi, Corrosion Specialist at the following test points: nhandle Take point Panhandle -1.81vdc / Ameren -1.67vdc P Ameren side -1.04vdc tt Dr1.166vdc hland Dr South -1.156vdc hland Circle -1.167vdc ary's -1.320vdc	Not Applicable
The following pipe to so T-002-006-TP at the Pa Take point T-002-005-T T-002-002-TP 9 Hillcres T-002-003-TP 404 Sour T-002-007-TP 601 Sour T-001-024-TP Proud M 192.465(b) General Comment:	il readings were also obtained by Fred Halibi, Corrosion Specialist at the following test points: nhandle Take point Panhandle -1.81vdc / Ameren -1.67vdc P Ameren side -1.04vdc tt Dr1.166vdc hland Dr South -1.156vdc hland Circle -1.167vdc ary's -1.320vdc	Not Applicable
The following pipe to so T-002-006-TP at the Pa Take point T-002-005-T T-002-002-TP 9 Hillcres T-002-003-TP 404 Sour T-002-007-TP 601 Sour T-001-024-TP Proud M 192.465(b) General Comment: There were no rectifier	il readings were also obtained by Fred Halibi, Corrosion Specialist at the following test points: nhandle Take point Panhandle -1.81vdc / Ameren -1.67vdc P Ameren side -1.04vdc st Dr1.166vdc hland Dr South -1.156vdc hland Circle -1.167vdc ary's -1.320vdc Were rectifier installations inspected?	Not Applicable Not Applicable
The following pipe to so T-002-006-TP at the Pa Take point T-002-005-T T-002-002-TP 9 Hillcres T-002-003-TP 404 Sour T-002-007-TP 601 Sour T-001-024-TP Proud M 192.465(b) General Comment:	il readings were also obtained by Fred Halibi, Corrosion Specialist at the following test points: nhandle Take point Panhandle -1.81vdc / Ameren -1.67vdc P Ameren side -1.04vdc st Dr1.166vdc hland Dr South -1.156vdc hland Circle -1.167vdc ary's -1.320vdc Were rectifier installations inspected? Installations to inspect during this audit.	•
The following pipe to so T-002-006-TP at the Pa Take point T-002-005-T T-002-002-TP 9 Hillcret T-002-003-TP 404 Sout T-002-007-TP 601 Sout T-001-024-TP Proud M. 192.465(b) General Comment: There were no rectifier to 192.465(a) General Comment:	il readings were also obtained by Fred Halibi, Corrosion Specialist at the following test points: nhandle Take point Panhandle -1.81vdc / Ameren -1.67vdc P Ameren side -1.04vdc st Dr1.166vdc hland Dr South -1.156vdc hland Circle -1.167vdc ary's -1.320vdc Were rectifier installations inspected? Installations to inspect during this audit.	

192.465(c)

Not Applicable

Were critical/non critical bonds tested?

General Comment:		
There were no critical/i	non critical bonds available to test during this audit.	
192.467(a)	Is electrical isolation provided by use of insulated meter spud, valve, union, or flange?	Satisfactory
192.467(c)	Were casings installations tested for electrical isolation?	Not Checked
General Comment:		
No casing installations	were inspected during this audit.	
192.479(a)	Is the above ground piping coated or painted as required?	Satisfactory
192.479(c)	Is the pipeline free of corrosion or pitting?	Satisfactory
	DAMAGE PREVENTION	Status
Category Comment:		
Each road crossing an	d the pressure station noted in this report were properly marked as required.	
192.614	Does the operator have a valid notification of planned excavation activities?	Not Applicable
General Comment:		
The operator did not ha	ave a valid notification of planned excavation activities at the time of this audit.	
ADM. CODE 265.40(a)	Did the operator complete the locating activities in the specified timeframe?	Not Applicable
General Comment:		
The operator did not ha	ave a valid notification of planned excavation activities at the time of this audit.	
192.614(c)(5)	Were temporary markings made in accordance with the operator's Operation and Maintenance Manual?	Not Applicable
General Comment:		
The operator did not ha	ave a valid notification of planned excavation activities at the time of this audit.	
192.707(a)(1)	Are line markers placed and maintained as close as practical over each buried main and transmission line located at each crossing of a public road and railroad?	Not Applicable
192.707(a)(2)	Are line markers placed and maintained as close as practical over each buried main and transmission line located wherever necessary to identify the location of the transmission line or main to reduce the possibility of damage or interference?	Satisfactory
192.707(c)	Are line markers placed and maintained as close as practical over each buried main and transmission line located above ground?	Satisfactory
192.707(d)(1)	Do the operator's line markers contain the following information: The following	Satisfactory

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

	,	
	must be written legibly on a background of sharply contrasting color on each line marker: The word "Warning," "Caution," or "Danger" followed by the words "Gas (or name of gas transported) Pipeline" all of which, except for markers in heavily developed urban areas, must be in letters at least 1 inch (25 millimeters) high with ¼ inch (6.4 millimeters) stroke?	
192.707(d)(2)	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The name and phone number (including area code) of the operator where the operator can be reached at all times?	Satisfactory
PRESSUR	E LIMITING AND REGULATING DEVICES (MECHANICAL)	Status
Category Comment:		
	n RT 36 to Egyptian Road Station X-038 was inspected during this audit. The Pressure Control Station Indept. The Pressure Control Station Indept. MAOP, inspection dates, and set point. Pressure readings taken at the stations indicate the stations a	
192.739(a)(4)	Was each pressure limiting station, relief device (except rupture discs), and pressure regulating station and its equipment subjected at intervals not exceeding 15 months, but at least once each calendar year, to inspections and tests to determine that it is properly installed and protected from dirt, liquids, or other conditions that might prevent proper operation.?	Satisfactory
192.317(b)	Is each above ground transmission line or main protected from accidental damage by vehicular traffic or other similar causes?	Satisfactory
192.741(a),192.741(c)	Were telemetering and/or recording gauges inspected for abnormally high or low pressure indications?	Satisfactory
192.743(a)	Is overpressure protection provided on the pipeline down stream of the take point?	Satisfactory
General Comment:		
Overpressure protection pro	ovided by Trunkline.	
192.199(d)	Did the pressure relief or pressure limiting devices inspected to determine if the support was made of noncombustible material?	Satisfactory
192.199(e)	Did the pressure relief or pressure limiting devices inspected to determine if the discharge stacks, vents, or outlet ports were designed to prevent accumulation of water, ice, or snow, and located where gas can be discharged into the atmosphere without undue hazard?	Satisfactory
192.199(h)	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?	Satisfactory
	VALVE MAINTENANCE	Status
Category Comment:		
TD-34-02-002 in the alley of	oressure station were inspected during this audit. Also inspected were valves TD-35-03-001 at Rt. 36 and a FPembroke at Main St, TD-34-02-002 in the alley of Parke between Pembroke and Sale, and TD-34-02-00 Valve Location and Record forms were used to verify location, inspection compliance and equipment.	
	Were the valves inspected accessible?	Satisfactory

AMEREN ILLINOIS COMPANY/9-28-2012

	ODORIZATION OF GAS	Status
Category Comment:		•
	erformed by John Reardon at Jarman Center on the 700 block of Main St. in Tuscola utilizing a Heath Odorato Gas was detected at 0.36% gas in air.	or model 5637 S/N 1763 last
192.625(a)	Was the odor intensity level readily detectable at or below 1/5th LEL?	Satisfactory
192.625(e)	Was the Odorization equipment and tank levels inspected?	Satisfactory
192.625(f)	Was the operator's equipment calibrated as required?	Satisfactory
TRANSMISSION		Status
Category Comment:		•
The Tuscola system of	loes not contain transmission valves.	
192.179(b)(1)	Are transmission valves protected from tampering or damage?	Not Applicable
192.745(a)	Were the valves inspected accessible?	Not Applicable
192.719(a)	Is pre-tested transmission pipe inventory maintained for use in an emergency?	Not Applicable
MARKING OF MATERIAL		Status
192.63(a)	Does the operator's components and pipe contain the required markings?	Satisfactory
OPERATOR QUALIFICATION		Satisfactory
		Status